


### Accessories supplied with Furnaks device

List of required accessories for Ash analysis is as below. All the accessories may be obtained from our company after the sale.



No	Description	Quantity
1	Porcelain Crucible	6
2	Desiccator, 210 mm	1
3	Silica Gel, 1 Kg	1
4	Tongs	1
5	Burn-Proof Gloves	1



### Recommended Machinery and Equipment



#### Precision Balance (0.0001 Sensitive)

Accurate measurement of sample quantity is an important factor in terms of analysis results. Therefore, reliable and appropriately sensitive scales should be used. Our company provides scales to our customers upon request.